Ukiah Fire Station #2 1800 North State Street Ukiah, CA 95482 Case No. 1TMC164

Notice of No Further Action related to Petroleum Discharges:

Comment Period ends December 3, 2003

Problem Description:

Three 1,000-gallon underground storage tanks were removed on July 30, 1991. Soil and groundwater sampled at the time of tank removal indicated that there was a release of petroleum hydrocarbons to the groundwater. Petroleum impacted soils were excavated and removed from the tank pit area as well as the product lined trenches in 1991.

Environmental Investigation:

In 2002 a soil and groundwater investigation was conducted. Soil and groundwater was sampled from nine locations surrounding the former tank and product lines. Analysis of the soil and groundwater samples showed no detections of any petroleum hydrocarbon constituents, including gasoline, diesel, benzene or methyl tertiary butyl ether (MTBE).

MTBE Status:

Groundwater was analyzed for MTBE and never detected above the laboratory reporting limits.

This case will be closed without further notice unless significant public comment is received prior to December 3, 2003. Please contact Beth Lamb at (707) 576-2669 if you have any questions.

BML:js/Ukiah Fire 30 day ltr